Date: **5 May 2021**
Product: **Hughes 9502**
Release: **5.9.6.4**
Importance: Recommended

Software version 5.9.6.4 for the Hughes 9502 terminal is a recommended upgrade with a few enhancements.

The upgrader file name is **9502_Upgrader_5_9_6_4_PC.exe** and is available on the Hughes BGAN support page: http://www.bgan.hughes.com
Alternatively, the software can be downloaded over the air from the Inmarsat upgrade server by using the Remote SMS feature and the ATCO command _IGETFW.

**Release Notes for 5.9.6.4 (Since 5.9.6.2)**

**Enhancements**

- Fixed an issue where the NAPT context was not activated after the unit recovered from an Inmarsat network outage. This network outage uncovered a rare attach scenario that did not trigger the activation of the shared PDP context in NAPT mode.
- Fixed an issue where the username and password for a custom (non-default) APN were not saved when defining an ACA context on the ACA Web page.
- Removed the Features Web page and added an Enhanced Security configuration option to the Security page. Feature codes are no longer required.
- Fixed a hole in enhanced security that could allow local access.
- Fixed Web UI issue where for some operations (such as reboot) it appeared the UI accepted an incorrect Admin password and performed the requested operation though it actually did not.
- Fixed Web UI issue with dynamic entry of APN password
- The release includes BPS 2.4.19.
- The SVN for this release is 21.

Should you have any questions regarding this notice please do not hesitate to contact Hughes at mobilesatellitesupport@hughes.com