

Date:12 October 2022Product:Hughes 9450LW and 9450TWRelease:6.7.2.2Importance:Recommended

Software version 6.7.2.2 for the Hughes 9450LW and TW terminals is a recommended upgrade with some new features.

The 6.7.2.2 upgrader will be available through both the Inmarsat support page: <u>www.inmarsat.com/support/bgan-firmware/</u> and the Hughes BGAN support page: <u>bgan.hughes.com</u>

Release Notes for 6.7.2.2 (Since 6.7.1.2)

Enhancements and Bug Fixes

- Added a Location Based Services feature which is configured from the new Location Services page in the Settings section of the Web UI. See Rev C of the 9400 Series User Guide for more information.
- Added an ATC/LTE Robustness feature to the General Settings page. This can be turned on to improve the UT's receive signal when operated near interfering signals.
- Corrected handling of APN username and passwords on the Web UI.
- Removed restrictions when configuring the UT IP address and allow 0-255 for each octet.
- Reset to factory defaults when pressing the boot mode button during power down.
- Improved satellite blockage recovery and recovery in the presence of interferers.
- Support AT commands on IP port 5454 as well as 1829.

Should you have any questions regarding this notice please do not hesitate to contact Hughes at <u>mobilesatellitesupport@hughes.com</u>